

Inspection Photos

4/05/2023

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location #334138

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334138



Photo 1: Photos taken from the Location entrance. Photo shows Operator appears to have re-graded the working pad- regrading alone is inadequate to provide long-term stabilization, minimization of degradation, tracking and off-site sediment transport, and is considered a temporary repair measure.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334138



Photo 2: Photo taken from the access road entrance. Photo shows Operator has implemented a single row of “reusable trackout control mats”. BMP is not per good engineering practices, and is inadequate in length to allow for at least an entire tire rotation for most off-highway, or industrial vehicle tires used in O&G.