

Inspection Photos

4/05/2023

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location #334393

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334393



Photo 1: Photos 1-3 taken from the Location. Photos show BMPs to stabilization the Location, and to minimize erosion, degradation and off-site sediment transport remain missing or insufficient.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334393



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334393




Photo 3: See comments under photo 1.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334393



April 5, 2023

Photo 4: Photo taken from the access road entrance ~1/2 south of the Location. Photo shows Operator has implemented a single row of “reusable trackout control mats”. BMP is not per good engineering practices, and is inadequate in length to allow for allow for at least an entire tire rotation for most off-highway, or industrial vehicle tires used in O&G.