

Inspection Photos

4/05/2023

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location #334745

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334745



Photo 1: Photos 1-3 taken from the access road entrance and Stone Quarry Road. Photo shows Operator has implemented a single row of “reusable trackout control mats”. BMP is not per good engineering practices, and is inadequate in length to allow for at least an entire tire rotation for most off-highway, or industrial vehicle tires used in O&G. Photo also shows that Operator is traveling around the VTC (yellow dotted lines), resulting in continued sediment transport onto the public roadway.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334745



Photo 2: See comments under photo 1. Photo shows sediment transport from the Location onto the public roadway has persisted.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334745



April 5, 2023

Photo 3: See comments under photo 1. Photo shows sediment transport from the Location onto the public roadway has persisted.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334745



April 5, 2023

Photo 4: Photos 4-5 show BMPs to stabilize the Location, and to minimize erosion, degradation and off-site sediment transport remain missing or insufficient; pad lacks stabilization.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334745



April 5, 2023



April 5, 2023

Photo 5: See comments under photo 4.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334745



Photo 6: Photos taken from the northeast end of the Location. Photo shows erosion degradation on the interim areas of the Location, due to runoff from the working pad; BMPs to manage runoff from the working pad remain missing or insufficient;

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334745



Photo 7: See comments under photo 4.