

# Inspection Photos

4/05/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #422301

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #422301



April 5, 2023



April 5, 2023

**Photo 1:** Location overview.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #422301



April 5, 2023



April 5, 2023

**Photo 2:** Photos taken from the cut slopes on the southwest end of the Location. Photos show slopes lack stabilization- erosion degradation evident.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #422301



**Photo 3:** Photos taken from the cut slopes on the southwest end of the Location. Photos show slopes lack stabilization- erosion degradation evident.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #422301



**Photo 4:** Photo shows sediment deposition due to unstabilized cut slopes.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #422301



**Photo 5:** Photo shows sediment deposition due to unstabilized cut slopes.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #422301



**Photo 6:** Photos containment BMP at methanol tank has filled with fluids, and is no longer adequate to contain a spill.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #422301



April 5, 2023



April 5, 2023

**Photo 7:** Safety fence in disrepair.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #422301



**Photo 8:** Signage remains missing from tank battery on the northwest end of the Location.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #422301



**Photo 9:** Anchors lack required marking.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #422301



**Photo 10:** Anchors lack required marking.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #422301



**Photo 11:** Backfilling excavation in process. BMPs at excavated soils not observed.