

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2023

Submitted Date:

04/12/2023

Document Number:

690204086

**FIELD INSPECTION FORM**Loc ID 324497 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone | Email                    | Comment |
|---------------|-------|--------------------------|---------|
| NEWVILLE TONI |       | toni_newville@oxy.com    |         |
| OXY           |       | COGCCinspections@oxy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name               | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 211802      | WELL | PR     | 06/01/2022  | CO2        | 055-06037 | SHEEP MOUNTAIN UNIT<br>13-1 | RI          |

**General Comment:**

On 4/10/2023, Ryan Costa conducted a follow up location inspection.  
See attached photos and additional details within this report.

**Location**

|                    |   |       |            |
|--------------------|---|-------|------------|
| <b>Lease Road:</b> |   |       |            |
| Type               | Main  |       |            |
| comment:           | The road has been widened causing additional disturbance and has pushed gravel material off the road that needs to be removed. There are also metal rebar that have been pulled up. |       |            |
| Corrective Action: | Comply with 1002.e.f. rules to minimize disturbance. Remove or repair rebar markers. Remove sediment material that was graded off the road.   | Date: | 05/01/2023 |

Overall Good: ☐

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             |          |       |  |
| Corrective Action:   |          | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           | The gravel pile at the location was mostly moved onto the roadway. |       |  |
| Corrective Action: |  | Date: |  |

Overall Good: ☐

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 690204087    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079653">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079653</a> |