

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403345003

Date Received:

03/14/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

7 of 8 CAs from the FIR responded to on this Form

7 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Sanford, Anita</u>		<u>Anita.Sanford@scoutep.com</u>
<u>Olson, Andrew</u>	<u>(970) 257-6079</u>	<u>andrewolson@chevron.com</u>
<u>Patterson, Chris</u>	<u>970-620-3456</u>	<u>Chris.Patterson@scoutep.com</u>
<u>Arthur, Denise</u>		<u>denise.arthur@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204758

Inspection Date: 03/13/2023

FIR Submit Date: 03/13/2023

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 314696

Location Name: MCLAUGHLIN, A C-62N103W Number: 14SWSW County: \_\_\_\_\_

Qtrqr: SWS Sec: 14 Twp: 2N Range: 103W Meridian: 6  
W

Latitude: 40.136290 Longitude: -108.932740

FACILITY - API Number: 05-103- -00 Facility ID: 314696

Facility Name: MCLAUGHLIN, A C-62N103W Number: 14SWSW

Qtrqr: SWS Sec: 14 Twp: 2N Range: 103W Meridian: 6  
W

Latitude: 40.136290 Longitude: -108.932740

CORRECTIVE ACTIONS:

1 ☒ CA# 168057

Corrective Action: Clean up and remove stained soils per Rule 912.a.

Date: 04/13/2023

Response: CA COMPLETED

Date of Completion: 03/13/2023

Operator Comment: All E&P waste was handled according to the 900 Series rules.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 168058

Corrective Action: Comply with Rule 406.e.(1)

Date: 03/13/2023

Response: CA COMPLETED

Date of Completion: 03/13/2023

Operator Comment: Grading was repaired and installed.

COGCC Decision: Approved

COGCC Representative: Approved per inspection 696204791.

3 ☒ CA# 168059

Corrective Action: Implement BMPs and properly store equipment in a manner that minimizes pollution.

Date: 03/13/2023

Response: CA COMPLETED

Date of Completion: 03/13/2023

Operator Comment: Equipment was removed, cleaned up and properly stored.

COGCC Decision: Approved

COGCC Representative: Approved per inspection 696204791.

4 ☒ CA# 168060

Corrective Action: Comply with Rule 606.

Date: 03/20/2023

Response: CA COMPLETED

Date of Completion: 03/13/2023

Operator Comment: All non-essential equipment, supplies, weeds, rubbish, and other waste material has been removed.

COGCC Decision: Approved

COGCC Representative: Approved per inspection 696204791.

5 ☒ CA# 168061

Corrective Action: Install sign to comply with Rule 605.h.

Date: 04/14/2023

Response: CA COMPLETED

Date of Completion: 03/13/2023

Operator Comment: Tank label has been applied.

COGCC Decision: **Not Approved**

Based on photos provided by Operator, tanks remain out of compliance with Rule 605.h. Inspection #696204791

COGCC Representative: observed that tanks had been removed from the Location therefore CA is no longer applicable for this Location, though it is note that the CA was not resolved.

Per inspection #696204793, the two tanks appear to have been placed on Location #314697 where it has been documented that the tanks remain out of compliance with Rule 605.h.

6 ☒ CA# 168062

Corrective Action: Comply with 1002.e and restrict vehicle travel to the designated working pad and access road. See "Interim Reclamation" for corrective action related to the reclamation of the disturbed areas.

Date: 03/13/2023

Response: CA COMPLETED

Date of Completion: 03/13/2023

Operator Comment: Impacts to land disturbance has been repaired. Travel is restricted.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Per inspection #696204791, Operator has fenced off disturbed areas to restrict travel, though Reclamation Specialist disagrees that areas have been "repaired", and reclamation requirements remain applicable.

8 ☒ CA# 168064

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 03/13/2023

Response: CA COMPLETED

Date of Completion: 03/13/2023

Operator Comment: Roadbase has been installed to minimize tracking, when conditions allow further improvements will be made.

COGCC Decision: **Not Approved**

COGCC Representative: Per inspection #696204791, work to comply with Rule 1002.f remains inadequate; tracking and stormwater issues persist; regrading alone insufficient; BMPs at soil stockpiles remained missing or insufficient.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: RESOLUTION PICTURES ATTACHED

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Anita Sanford

Signed: \_\_\_\_\_

Title: Regulatory Analyst

Date: 3/14/2023 12:04:53 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403345003	FIR RESOLUTION SUBMITTED
403345431	FIRR CA PICTURES

Total Attach: 2 Files