

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403360206

Date Received:
03/30/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 6 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Sanford, Anita</u>		<u>Anita.Sanford@scoutep.com</u>
<u>Patterson, Chris</u>		<u>Chris.Patterson@scoutep.com</u>
<u>Olson, Andrew</u>	<u>(970) 257-6079</u>	<u>andrewolson@chevron.com</u>
<u>Neidel, Kris</u>		<u>kris.neidel@state.co.us</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204793

Inspection Date: 03/24/2023

FIR Submit Date: 03/27/2023

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 314697

Location Name: MCLAUGHLIN, A C-62N103W Number: 14SESW County: _____

Qtrqtr: SESW Sec: 14 Twp: 2N Range: 103W Meridian: 6

Latitude: 40.139490 Longitude: -108.928130

FACILITY - API Number: 05-103- -00 Facility ID: 314697

Facility Name: MCLAUGHLIN, A C-62N103W Number: 14SESW

Qtrqtr: SESW Sec: 14 Twp: 2N Range: 103W Meridian: 6

Latitude: 40.139490 Longitude: -108.928130

CORRECTIVE ACTIONS:

6 CA# 168602

Corrective Action: Comply with Rule 1002.f.(2)

Date: 03/29/2023

Response: CA COMPLETED

Date of Completion: 03/29/2023

Operator Comment: Brought in material and compaction equipment to help stabilize, as well as to minimize degradation, tracking and offsite sediment transport. Access road from highway is closed until conditions improve and additional BMPs can be put in place. Brought soils back into bermed areas.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed; based on photo provided, BMPs do not appear to be sufficient. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see Attachments

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson Signed: _____

Title: Sr. HSE Coordinator Date: 3/30/2023 7:55:04 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403360206	FIR RESOLUTION SUBMITTED
403360221	PIC
403360222	PIC

Total Attach: 3 Files