

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/03/2023

Submitted Date:

04/07/2023

Document Number:

708200117

FIELD INSPECTION FORMLoc ID 483130 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10360

Name of Operator: NAVEX RESOURCES LLC

Address: 1020 E LEVEE STREET, SUITE 130

City: DALLAS State: TX Zip: 75207

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
WALTERS, LEANN		lwalters@trekresources.com	
BIEKER, MARK		mabieker@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483130	LOCATION	AC			-	Pfaffly 1-12	CI
483495	WELL	AP	12/19/2022		063-06353	Pfaffly 1-12	CI

General Comment:

This is a Construction and Stormwater Inspection in response to Form 42: Notice of Construction- Document #403353314.

Location Construction

Location ID: 483130 CDP: _____

Comment:

Corrective Action: Date: _____

Form 2A COAs:

Comment:

Corrective Action: Date: _____

Wildlife BMPs:

Comment:

Corrective Action: Date: _____

Comment:

Corrective
Action: Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____
Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	483130	Type:	LOCATION	API Number: -	Status:	AC	Insp. Status:	CI	
Facility ID:	483495	Type:	WELL	API Number:	063-06353	Status:	AP	Insp. Status:	CI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION Fail

Comment

At the time of this inspection, Staff observed that approximately 3" of topsoil had been salvaged from the access road portion and stored along the southern side of the road. Staff estimates that approximately 5" of topsoil remain along the access road that will need to be salvaged and stockpiled to be in compliance with Rule 1002.b. It appears that all topsoil has been salvaged from the facility/pad areas and stored around the north, west, and south sides. Refer to attached inspection photos for documentation.

Corrective Action

Operator shall comply with Rule 1002.b and salvage all (remaining) topsoil from the access road. Corrective action date is the date the location was observed out of compliance.

Date **04/03/2023**1002c. PROTECTION OF SOILS Pass

Comment

Topsoil from the drilling pad has been temporarily stabilized with equipment tracking for short term stabilization. Operator shall implement long-term stabilization BMPs (i.e., seeding when appropriate) when stabilizing all stockpiles to ensure compliance under Rule 1002.c. Topsoil salvaged from the access road shall also have stabilization BMPs implemented once all topsoil has been salvaged.

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION Pass

Comment

Per Rule 1002.e.(1), Operator has adequately constructed and stabilized the entire well pad area, including cut and fill slopes, to control dust and minimize erosion. A disturbance area of 3.04 acres was mapped using OnX mapping application; this appears to be in compliance with the approved Form 2A for the permitted disturbance area.

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Operator shall comply with interim reclamation timing requirements.

Corrective Action _____ Date _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Temporary BMPs have been installed around the entire perimeter during the construction phase of the location. Staff observed straw wattles located around the construction area in addition to surface roughening and a stormwater ditch with sediment trap on the northeast corner (downslope) of the pad. More permanent BMPs should be installed upon the completion of pad construction. A follow-up stormwater inspection will be conducted at a future date to ensure compliance with Rule 1002.f. standards. Refer to the COGCC Comments section for additional stormwater compliance information.

Corrective Action: Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Per Rule 1002.f., oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004. Operators shall employ BMPs, as necessary to comply with this rule, at all oil and gas locations, including, but not limited to, well pads, soil stock piles, access roads, tank batteries, compressor stations, and pipeline rights of way. BMPs shall be selected based on site specific conditions, such as slope, vegetation cover, and proximity to water bodies, and may include maintaining in-place some or all of the BMPs installed during the construction phase of the facility. Where applicable based on site-specific conditions, operators shall implement BMPs in accordance with good engineering practices.	edwardsond	04/07/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403368466	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6075759
708200118	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6075757