

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2023

Submitted Date:

04/10/2023

Document Number:

697504593

**FIELD INSPECTION FORM**Loc ID 421908 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10665

Name of Operator: CCRP OPERATING INC

Address: 12136 W BAYAUD AVE STE 320

City: LAKEWOOD State: CO Zip: 80228

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		dustin@uplandexploration.com	
		martin@rockiesresourcesllc.com	
		david@uplandexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421912	WELL	SI	02/01/2021	OW	123-33110	Wagner 11-65 11-1H	RI

**General Comment:**

This is a Stormwater Inspection for a shared access road addressing a previous corrective action along a portion of the access road that crosses a High Priority Habitat (Aquatic Native Species Conservation Waters) at Geary Creek.

An inspection was performed back on February 10, 2023 for Upland Exploration. At that time, COGCC staff, Chris Binschus, only issued a corrective action to Upland Exploration. It was brought to COGCC's attention on 4/7/2023 that this was a shared access road.

### Location Construction

Location ID: 421908 CDP: \_\_\_\_\_

Comment: The Access Road Map within the Location file is not accurate- see Doc.# 2530506.

Corrective Action: Operator shall submit an accurate access road map via Form 4 Sundry Notice.

Date: 04/24/2023

#### Form 2A COAs:

Comment:

Corrective Action:

Date: \_\_\_\_\_

#### Wildlife BMPs:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Comment:

Corrective  
Action:

Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: At the time of the inspection on 2/10/2023, sediment discharge into Geary Creek from the access road was observed. Portions of the access road, east of Geary Creek, are not sufficiently stabilized and the south-facing fill slopes leading into Geary Creek are not stabilized. Operator has failed to prevent transport of sediment into a High Priority Habitat (Aquatic Native Species Conservation Waters). Refer to Photos 1-4.

Upland Exploration is in-process of completing the corrective action work but it is not complete.

Corrective Action: CCRP shall coordinate with Upland Exploration on the corrective action work to comply with Rule 1002.f.

The corrective action date is the date the issue was observed out of compliance.

Date: 02/10/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403369532	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6077368">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6077368</a>
697504594	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6077367">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6077367</a>