

TEP ROCKY MOUNTAIN LLC, SPECIALTY RESTAURANTS-67S96W/35NWNW

Location # 334114



Wellheads – Photo #02227



Separators – Photo #02235

TEP ROCKY MOUNTAIN LLC, SPECIALTY RESTAURANTS-67S96W/35NWNW

Location # 334114



Tank Battery – Photo #02229



Rill Erosion onto Location – Photo #02231

TEP ROCKY MOUNTAIN LLC, SPECIALTY RESTAURANTS-67S96W/35NWNW

Location # 334114



Rill Erosion onto Location – Photo #02233