



00325601

# COLORADO OIL & GAS CONSERVATION COMMISSION

## FIELD INSPECTION REPORT

☒ NOTICE OF UNSATISFACTORY INSPECTION

☐ NOTICE OF SATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100

API No. 05- 121 - 9638

LEASE NAME: Landaker #2

LOCATION: SESE 18-35-55W

OPERATOR: H+R

DATE: 9-30-96

INSPECTOR: EBBird

Insp. Type: CA

Insp. Status: PA

PA: Y

(N)

Pass/Fail: P

(F)

Viol.: Y

(N)

NOV: Y

(N)

## INSPECTION ITEM

## COMMENTS

## INPUT

<b>Well ID Signs</b> (Rule 210, 604.c(4))	Well cemented by H+R	✓
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)		
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)	H+R	
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	incomplete / compacted grass	—
<b>Miscellaneous</b>		

## CORRECTIVE ACTION REQUIRED:

Remove equipment and  
restore site within 6 months.

Date Corrective Action Required By: 3-30-97

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.