

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403379932

Date Received:  
04/20/2023

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: CIVITAS NORTH LLC

Address: 555 17TH STREET #3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Mike Storey

970-939-6353

mstorey@civiresources.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708200130

Inspection Date: 04/10/2023

FIR Submit Date: 04/17/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: CIVITAS NORTH LLC

Company Number: 10661

Address: 555 17TH STREET #3700

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 476815

Location Name: Allred 8-59 Number: 30 County: \_\_\_\_\_

Qtrqr: NENW Sec: 30 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.638789 Longitude: -104.021999

### FACILITY - API Number: 05-123-00 Facility ID: 476815

Facility Name: Allred 8-59 Number: 30

Qtrqr: NENW Sec: 30 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.638789 Longitude: -104.021999

### CORRECTIVE ACTIONS:

1 CA# 169645

Corrective Action: Comply with Rule 606 and remove weedy debris from around equipment.

Date: 04/24/2023

Response: CA COMPLETED

Date of Completion: 04/19/2023

Operator Comment: Weeds were removed/mowed on 4/19/2023. The location now complies with Rule 606.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 169646

Corrective Action: Comply with Rule 606 and remove all trash from location.

Date: 04/24/2023

Response: CA COMPLETED

Date of Completion: 04/19/2023

Operator Comment: Trash on perimeter fences has been cleaned-up and removed as of 4/19/2023 to comply with Rule 606.

COGCC Decision:

COGCC  
Representative:

3 CA# 169647

Corrective Action: Comply with Rule 606 and remove equipment from location.

Date: 04/24/2023

Response: CA COMPLETED

Date of Completion: 04/19/2023

Operator Comment: Equipment noted during inspection has been removed as of 4/19/2023 to comply with Rule 606.

COGCC Decision:

COGCC  
Representative:

4 CA# 169648

Corrective Action: Comply with Rule 1002.f.(2) to repair, maintain, and/or install BMPs in accordance with good engineering practices.

Date: 04/19/2023

Response: CA COMPLETED

Date of Completion: 04/19/2023

Operator Comment: As of 4/19/2023, Operator has removed filtrex wattles that were noted as deteriorating, and rill erosion has been raked in and the areas were over seeded. Operator will continue to maintain and/or install BMPs in accordance with good engineering practices to help minimize erosion and site degradation as outlined in Rule 1002.f.(2)

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed:

Title: Sr Regulatory Analyst

Date: 4/20/2023 11:56:54 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**    **Description**

403379940	Inspection Photos
-----------	-------------------

Total Attach: 1 Files