

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403385395

Date Received:

04/26/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Fischer, Alex

alex.fischer@state.co.us

-

RangelyRegulatory@scoutep.com

Patterson, Chris

Chris.Patterson@scoutep.com

Heil, John

john.heil@state.co.us

Sanford, Anita

Anita.Sanford@scoutep.com

Johnson, Mike

Mike.Johnson@scoutep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204864

Inspection Date: 04/24/2023

FIR Submit Date: 04/25/2023

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: OLD OPERATORS - STATUS UNKNOWN

Company Number: 99999

Address: SEE COMMENT LINE IN WELL

City: XXXXXXXX State: XX Zip: \_\_\_\_\_

LOCATION - Location ID: 479691

Location Name: RUNKNOWN Number: 33-18 County: \_\_\_\_\_

Qtrqr: NWS Sec: 33 Twp: 2N Range: 102W Meridian: 6  
W

Latitude: 40.099010 Longitude: -108.857060

FACILITY - API Number: 05-103-00 Facility ID: 479691

Facility Name: RUNKNOWN Number: 33-18

Qtrqr: NWS Sec: 33 Twp: 2N Range: 102W Meridian: 6  
W

Latitude: 40.099010 Longitude: -108.857060

CORRECTIVE ACTIONS:

1 CA# 170065

Corrective Action: Comply with Form 27(i) #402794463 COAs.

Date: 06/08/2023

Response: CA COMPLETED

Date of Completion: 04/25/2023

Operator Comment: As discussed with John Heil with the COGCC, on April 25th at 1:06 PM, this is an on going reclamation site, we had to stop shredding soil last fall due to snow and weather. We need to sample the site and run analytical results to see if the soil is under the Table 915-1 requirement. We are planning to do this when we have other areas to sample, if it is under the requirements, we will submit the appropriate Form 27S, if the soil analytical is not below the requirements, we will continue shredding the soil.

COGCC Decision:

COGCC Representative:

2 CA# 170066

Corrective Action: Within 48 hours, Operator shall:

Date: 04/27/2023

- 1) Contact NW EPS John Heil (John.heil@state.co.us)
- 2) Comply with Rule 913.g and send a Form 27 for change of Operator.
- 3) Comply with 913.b.(5)B.i and install fencing or cover at the excavation.
- 4) Comply with Rules 913.b.(5)B.ii and 1002.c, and install BMPs to protect the stockpile, as well as to minimize erosion, degradation and sediment transport.

Upon closure of the Facility, Operator is required to conduct final reclamation pursuant to Rules 913.b.(6) and 1004.a.

Response: CA COMPLETED

Date of Completion: 04/26/2023

Operator Comment: Talked with John Heil with the COGCC via phone call, on April 25th at 1:06 PM  
Summited F27 for change of operator DOC# 403383712.  
Installed fencing at excavation.  
Installed BMPs to protect the stockpile

COGCC Decision:

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attachments

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed:

Title: Sr. HSE Coordinator

Date: 4/26/2023 2:15:03 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403385476	PIC
403385477	PIC

Total Attach: 2 Files