

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2023

Submitted Date:

04/26/2023

Document Number:

702501210

FIELD INSPECTION FORM

Loc ID 316358 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Patterson, Chris		Chris.Patterson@scoutep.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268941	WELL	SI	12/01/2021	OW	103-10360	GRAY B 22X	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday, 4/26/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Scout Energy Management LLC on the Gray B 22X well, Location #316358, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority/Density Habitats.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to FIRR #403380534 submitted by Operator for Corrective Action from Inspection #702501109 on 4/6/23.

While there during normal production operations the following compliance issue was observed:

1. Blading of location and access roads does not address Stormwater BMPs needing to be implemented and maintained to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.
- Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911 / (970) 675-3700

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	Chemical tank on containment		
Corrective Action:		Date:	
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Accessible with valve		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	268941	Type:	WELL	API Number:	103-10360	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Submersible pump. Well is on Production. Well status - Shut In as of December 2021. Last Production - November 2021. Last Production reporting - January 2023.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
				Material Handling And Spill Prevention		
Berms						

Comment: Insufficient BMPs to prevent vehicle tracking and the control of potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: Provide proper BMPs to prevent vehicle tracking and to control sediment migration from location and lease road.

Date: 05/26/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501211	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094918