

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2023

Submitted Date:

04/27/2023

Document Number:

679605565**FIELD INSPECTION FORM**Loc ID 427917 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1775 SHERMAN STREET STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451097	WELL	PR	06/15/2019	OW	123-44987	Raindance FD 20-362HNX	PR

**General Comment:**[Form 9\(S\) in well file.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused/disconnected equipment. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	05/27/2023
Type	TRASH		
Comment:	Previous operator signage displayed. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	05/27/2023
Type	OTHER		
Comment:	Stained soil under master valve. See attached photo.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d.	Date:	05/27/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	6' chain link		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 451097 Type: WELL API Number: 123-44987 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary

\*\*Weather Conditions: sunny, wet ground

On Thursday, April 27, 2023 at approximately 09:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at RAINDANCE FC 20-362 HNX (PDC Energy), at API #: 05-123-44987 in WELD COUNTY Colorado.

While there, I observed a producing well.

During this inspection the following possible compliance issues were observed:

1. Previous operator signage displayed on wellhead. Remove to comply with Rule 606.

(Corrective Action Date: May 27, 2023) See attached photo #2.

2. It appears to be stained soil under master valve. Conduct maintenance on equipment, cleanup stained material and review self-inspection processes per Rule 1002.(2).d.

(Corrective Action Date: May 27, 2023) See attached photo #3.

3. Unused/disconnected valve at wellhead. Connect or remove from location per Rule 606.

(Corrective Action Date: May 27, 2023) See attached photo #3.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

santistb

04/27/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679605566	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6095492">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6095492</a>