

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403387486

Date Received:

04/28/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69805

Name of Operator: PETROX RESOURCES INC

Address: 12600 W COLFAX AVENUE #C-440

City: LAKEWOOD State: CO Zip: 80215

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Clark, Ryan</u>	<u>(303)803-3998</u>	<u>ryan@petrox-resources.com</u>
<u>Nystrom, Dusty</u>	<u>(505) 330-1328</u>	<u>nystrow@yahoo.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 712700059

Inspection Date: 04/26/2023

FIR Submit Date: 04/27/2023

FIR Status: _____

Inspected Operator Information:

Company Name: PETROX RESOURCES INC

Company Number: 69805

Address: 12600 W COLFAX AVENUE #C-440

City: LAKEWOOD State: CO Zip: 80215

LOCATION - Location ID: 378719

Location Name: CANDELARIA 33-5-N33N5W Number: 10NENW County: ARCHULETA

Qtrqtr: NENW Sec: 10 Twp: 33N Range: 5W Meridian: N

Latitude: 37.125951 Longitude: -107.380300

FACILITY - API Number: 05-007-00 Facility ID: 302120

Facility Name: CANDELARIA 33-5 Number: 10-1

Qtrqtr: NENW Sec: 10 Twp: 33N Range: 5W Meridian: N

Latitude: 37.125951 Longitude: -107.380300

CORRECTIVE ACTIONS:

1 ☒ CA# 170197

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).
Install liner material to ensure spill or released materials will be maintained with
containment structure per Rule 603.o.(3).

Date: 05/17/2023

Response: CA COMPLETED

Date of Completion: 05/05/2023

Operator Comment: This tank is not used for awhile and will be removed from the location in the next week.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 170198

Corrective Action: Rules 905, 906, 1002.f, 068.e. Immediately control the release of fluids and clean up any free fluids, contact area EPS Jaoson Kasola within 48 hours and clean up impacted material within 7 days.

Date: 05/03/2023

Response: CA COMPLETED

Date of Completion: 04/27/2023

Operator Comment: Stuffing box was tightened to stop gurgling. Impacted soil was removed and replaced. Please see attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

3 ☒ CA# 170199

Corrective Action: Install sign to comply with Rule 605.a.

Date: 06/27/2023

Response: CA COMPLETED

Date of Completion: 05/01/2023

Operator Comment: New sign was ordered and will be updated in a few days.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Clark

Signed: _____

Title: V.P. Engineering

Date: 4/28/2023 7:40:51 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403387486	FIR RESOLUTION SUBMITTED
403387491	Corrective Action Photos

Total Attach: 2 Files