

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 40-20 Pad

Location ID: 335154



Photo # 6542 From entrance to location



Photo # 6543 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 40-20 Pad

Location ID: 335154



Photo # 6544 Location



Photo # 6545 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 40-20 Pad

Location ID: 335154



Photo # 6546 Location



Photo # 4257 From inspection 708900217 conducted on 04/04/2023 Meter calibration info not conspicuously posted

**Inspection Photos**  
**Location Name: TEP ROCKY MOUNTAIN LLC RMV 40-20 Pad**  
**Location ID: 335154**



**Photo # 6548 Meter calibration info not conspicuously posted**



**Photo # 6550 Stained soils & gravel on location**

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 40-20 Pad

Location ID: 335154



Photo # 6551 Stained soils & gravel on location

Photo # 6556 Containment liner needs maintenance

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 40-20 Pad

Location ID: 335154



Photo # 6559 Containment liner needs maintenance



Photo # 6561 Containment liner needs maintenance