

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403389703

Date Received:
05/01/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10665

Name of Operator: CCRP OPERATING INC

Address: 12136 W BAYAUD AVE STE 320

City: LAKEWOOD State: CO Zip: 80228

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Jesse Martin

jmartin@rockiesresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697504593

Inspection Date: 04/10/2023

FIR Submit Date: 04/10/2023

FIR Status: _____

Inspected Operator Information:

Company Name: CCRP OPERATING INC

Company Number: 10665

Address: 12136 W BAYAUD AVE STE 320

City: LAKEWOOD State: CO Zip: 80228

LOCATION - Location ID: 421908

Location Name: Wagner Number: 11-65 11-1H County: _____

Qtrqr: SE Sec: 11 Twp: 11N Range: 65W Meridian: 6

SW

Latitude: 40.929619 Longitude: -104.631047

FACILITY - API Number: 05-123-00 Facility ID: 421908

Facility Name: Wagner Number: 11-65 11-1H

Qtrqr: SE Sec: 11 Twp: 11N Range: 65W Meridian: 6

SW

Latitude: 40.929619 Longitude: -104.631047

CORRECTIVE ACTIONS:

1 CA# 169229

Corrective Action: Operator shall submit an accurate access road map via Form 4 Sundry Notice.

Date: 04/24/2023

Response: CA COMPLETED

Date of Completion: 04/24/2023

Operator Comment:

Form 4 was submitted on 04/24.2023, on Document #403375036 with the updated access road

COGCC Decision: _____

COGCC
Representative:

2 CA# 169230

Corrective Action: CCRP shall coordinate with Upland Exploration on the corrective action work to comply with Rule 1002.f.

Date: 02/10/2023

The corrective action date is the date the issue was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 05/01/2023

Operator
Comment:

CCRP had Standard Resources pull all sediment that was washed out back on the South side of the lease road of Geary Creek. They added 80+ tons of 10"+ Rip Rap from Granite Canyon to the South side to prevent future washout. Rock checks were added alongside the lease road on the Southwest side and one location on the Northwest side to mitigate erosion issues in the future.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr. Regulatory Analyst

Date: 5/1/2023 1:07:09 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403389802	Remediation
-----------	-------------

Total Attach: 1 Files