

Wagner Access Road- Geary Creek Drainage Corrective Action

CCRP had Standard Resources pull all sediment that was washed out back on the South side of the lease road of Geary Creek. They added 80+ tons of 10"+ Rip Rap from Granite Canyon to the South side to prevent future washout. Rock checks were added alongside the lease road on the Southwest side and one location on the Northwest side to mitigate erosion issues in the future.

COGCC Field Inspector Chris Binschus called on 4/27/2023 to express his appreciation for the quick response from CCRP, and said he would close the CA for CCRP.





Rock checks were added alongside the lease road on the Southwest side and one location on the Northwest side to mitigate erosion issues

