

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2023

Submitted Date:

05/01/2023

Document Number:

696204906

FIELD INSPECTION FORMLoc ID 413495 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10132

Name of Operator: GENESIS GAS & OIL LLC

Address: 1701 WALNUT STREET - 4TH FL

City: KANSAS CITY State: MO Zip: 64108

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		mvogt@genesigoco.com	
		jkarcz@genesigoco.com	
		j75rober@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412979	WELL	EP	04/10/2016	LO	103-11553	FGSU 4-12	RI
413495	LOCATION	AC			-	FLETCHER GULCH 4-12	RI

General Comment:

On 4/27/2023, Reclamation Specialist conducted an inspection at Genesis Gas & Oil Colorado LLC's FGSU 4-12 Location in Rio Blanco County, Colorado.

This inspection is a follow-up to #696203812 to document compliance with the following Corrective Actions:
-Final Reclamation

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and Corrective Actions.

The following additional issues were observed per this inspection:
-Stormwater

Refer to the "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules

Inspected Facilities									
Facility ID:	412979	Type:	WELL	API Number:	103-11553	Status:	EP	Insp. Status:	RI
Facility ID:	413495	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed **Fail**

Gravel removed _____

Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured **Fail**

Compaction alleviation **Fail** Dust and erosion control **Fail**

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: [See "COGCC Comments".](#)

Corrective Action: **Comply with Rule 1004.a and conduct final reclamation on the Location and access road.** Date **09/15/2022**

Overall Final Reclamation **Fail** Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: It was observed in this inspection that required stormwater and erosion control BMPs are missing or insufficient on the Location and access road.</p> <p>-Erosion degradation observed along cut slopes; slopes lack stabilization; BMPs to manage run-on, as to stabilize slopes inadequate.</p> <p>-Stormwater runoff from the location has resulted in gully erosion at the slopes on the north end of the Location; BMPs to allow for proper stormwater discharge in such a manner as to minimize erosion, degradation and off-site sediment transport inadequate.</p> <p>-Stormwater erosion, degradation and off-site sediment transport observed along the access road.</p> <p>Stormwater management required until final reclamation is achieved pursuant to 1004 Rules.</p>						
<p>Corrective Action: Comply with 1002.f. Install or repair required stormwater and erosion control BMPs at the Location and access road; temporary controls required until final reclamation work is performed, at which time additional BMPs will be required until long-term stabilization (such as revegetation) of the disturbances have been achieved. BMPs are required to be installed in accordance with Good Engineering Practices, and maintained in proper functioning condition at all times.</p>						<p>Date: 05/04/2023</p>
<p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

COGCC Comments

Comment	User	Date
<p>RECLAMATION COMMENT</p> <p>All Form 2 and Federal "permits to drill" on file for the Location have expired; Form 2 #400471709 expired 4/10/2016, Federal APD (doc. no 1828340) expired 7/31/2010.</p> <p>Inspection #696203812 observed that the Location has been constructed, and various surface equipment (pipe, risers, valve cellar) have been installed at the Location and along the access road; no wells have been drilled; work to maintain the Location and access road has not occurred. Location subject to Final Reclamation Requirements; inspection required Operator to comply with Rule 1004.a by 9/15/2022.</p> <p>It was observed in this inspection that final reclamation of the Location and access road has not been conducted; Location/Access road has not been decompacted, recontoured/regraded and reclaimed. Surface equipment along the road/Location has not been removed. Culverts along the access road remain, drainages have not been restored; Access road has continued to degrade. Fallen tree partially blocking access road at entrance.</p> <p>Original corrective action and date remains applicable: Submission of additional permits does not waive compliance with 1004 requirements- See "Notice to Operators: Interim Reclamation Procedures for Delayed Operations" dated January 5, 2017.</p>	trujilloam	05/01/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204907	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6099644