

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/25/2023

Submitted Date:

04/25/2023

Document Number:

702501188

**FIELD INSPECTION FORM**

Loc ID 316472 Inspector Name: Burchett, Kirby On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 760 HORIZON DRIVE STE 401  
City: GRAND JUNCTION State: CO Zip: 81506

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Patterson, Chris		Chris.Patterson@scoutep.com	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278283	WELL	PR	07/01/2022	OW	103-10595	A. C. MCLAUGHLIN 83X	PR

**General Comment:**

[COGCC Inspection Report Summary](#)

On Tuesday, 4/25/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Scout Energy Partners on the AC McLaughlin 83X well, Location #316472, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority and Density Habitats.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection is in response to FIRR #403379941 for Corrective Action from Inspection #702501075 on 4/5/23.

While there during normal production operations the following compliance issues were observed:

1. Blading of location and access road did not correct the need for Stormwater BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.  
Refer to attached photographs for Corrective Action.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Ancillary equipment	# 1		
Comment:	Chemical tank on containment		
Corrective Action:		Date:	
Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:	Accessible with valve. Gauge installed		
Corrective Action:		Date:	
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 278283 Type: WELL API Number: 103-10595 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Submersible pump](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				
		Culverts				
				Material Handling And Spill Prevention		

Comment: Insufficient Stormwater BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: Provide proper BMPs to prevent sediment migration from location and lease road.

Date: 05/25/2023

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403384302	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093512">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093512</a>
702501189	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093509">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093509</a>