

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403390940

Date Received:
05/02/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>ERIN JOSEPH</u>	<u>970-515-1169</u>	<u>COGCCinspections@oxy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690204080

Inspection Date: 04/10/2023

FIR Submit Date: 04/11/2023

FIR Status: _____

Inspected Operator Information:

Company Name: OXY USA INC

Company Number: 66561

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 324505

Location Name: SHEEP MOUNTAIN UNIT-628S70W Number: 2NENE County: HUERFANO

Qtrqtr: NENE Sec: 2 Twp: 28S Range: 70W Meridian: 6

Latitude: 37.647900 Longitude: -105.180570

FACILITY - API Number: 05-055-00 Facility ID: 211864

Facility Name: SHEEP MOUNTAIN UNIT Number: 12-2-E

Qtrqtr: NENE Sec: 2 Twp: 28S Range: 70W Meridian: 6

Latitude: 37.647900 Longitude: -105.180570

CORRECTIVE ACTIONS:

2 CA# 169256

Corrective Action: E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905.

Date: 04/13/2023

Response: CA COMPLETED

Date of Completion: 05/01/2023

Operator Comment: SEE ATTACHED
Excavated piles of impacted soil – It is in fact stored on top of a liner, it's just not visible since it's under the soil and the berms
Prairie Oilfield is scheduled to haul the soil off next week and will take pictures of the liner for verification.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Impacted soil was not stored properly as it was falling over top of the berms. Photos document liner was present however impacted soils are still present and need to be properly disposed per Rule 905. A follow up inspection will be performed.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: ERIN JOSEPH

Signed: _____

Title: REGUALTORY CONSULTANT

Date: 5/2/2023 9:22:53 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403390940	FIR RESOLUTION SUBMITTED
403390943	LOCATION PHOTOS

Total Attach: 2 Files