

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/03/2023

Submitted Date:

05/05/2023

Document Number:

708300376

FIELD INSPECTION FORMLoc ID 335018 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, LARAMIE		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289508	WELL	PR	01/13/2015	GW	045-13794	SHELL 797-09-12	PR
293266	WELL	PR	04/14/2015	GW	045-14926	SHELL 797-09-37A	PR
435700	WELL	PR	12/04/2014	GW	045-22291	Shell 797-09-HN1	PR

General Comment:**COGCC Inspection Report Summary**

On 5/3/2023 at approximately 10:55, Compliance Inspector Matthew Morris conducted a follow-up inspection at LARAMIE ENERGY LLC, Shell/797-09A at Location ID #335018 in Garfield County, Colorado.

Corrective actions from FIR #708300147 have been completed. Normal production operations were observed.

During the inspection, the following compliance issues were observed:

1) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/1-800-891-6191

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Pipe rail guards		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Pipe rail guards		
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 3		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:	No form of pressure monitoring equipment located on Bradenheads. All Bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:	Centralized containment					
Corrective Action:						
Date:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						
Date:						

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Centralized containment						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Centralized containment						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	289508	Type:	WELL	API Number:	045-13794	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	293266	Type:	WELL	API Number:	045-14926	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	435700	Type:	WELL	API Number:	045-22291	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Culverts				
		Ditches				
Waddles	Fail					BMP is degraded
		Berms				
		Sediment Traps				
				Material Handling And Spill Prevention		Chemical tank in containment
		Gravel				
		Compaction	Fail			Lease road lacks stabilization
		Other	Fail			Insufficient vehicle tracking BMPs
Sediment Traps						
Ditches						
Other	Fail					Insufficient vehicle tracking BMPs
Compaction	Fail					Location lacks stabilization

Comment: 1) Location lacks stabilization with insufficient vehicle tracking BMPs in place to minimize transportation of sediment
 2) Waddles installed to minimize sediment transportation from location have failed and need maintenance (northeast of separator units)
 3) Insufficient vehicle tracking BMPs in place at location entrance/exit to minimize transportation of sediment

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002

Date: 05/20/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708300377	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6106164