

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2023

Submitted Date:

05/01/2023

Document Number:

690204160

**FIELD INSPECTION FORM**

Loc ID: 308802    Inspector Name: COSTA, RYAN    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10758  
Name of Operator: OGRIS OPERATING LLC  
Address: PO BOX 53467  
City: MIDLAND    State: TX    Zip: 79710

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
WARD, GIENA		gward@ogrisop.com	
		timothy.thomsen@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282173	WELL	PR	12/22/2005	CBM	071-08656	GOLDEN EAGLE 32-5	RI

**General Comment:**

On 5/1/2023, Ryan Costa conducted a Location and Stormwater Management Inspection. See attached photos and additional details within this report.

**Location**

**Lease Road:**

Type Access

comment:

Corrective ActionL

Date:

Overall Good:

**Signs/Marker:**

Type WELLHEAD

Comment:

Corrective Action:

Date:

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: There is oily fluid in the engine skid that needs to be cleaned up.

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 05/05/2023

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403390216	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6099360">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6099360</a>
690204161	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6099345">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6099345</a>