

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2023

Submitted Date:

05/01/2023

Document Number:

690204164

FIELD INSPECTION FORMLoc ID 308799 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		timothy.thomsen@state.co.us	
WARD, GIENA		gward@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282123	WELL	PR	12/15/2005	CBM	071-08651	GOLDEN EAGLE 32-10	RI

General Comment:

On 5/1/2023, Ryan Costa conducted a Location and Stormwater Management Inspection.
See attached photos and additional details within this report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign does not have current operator info posted.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/31/2023

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:

Type	TRASH		
Comment:	There is some trash off the east side of the well pad.		
Corrective Action:	Comply with 606	Date:	05/05/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: There is oily fluid in the engine skid that needs to be cleaned up.

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 05/05/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403390224	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6099372
690204165	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6099347