


Stormwater Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /21SWSW
Location #: 323869



Location Overview: Location is located in a high priority habitat area.

Section/Township/Range:

Stormwater Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /21SWSW
Location #: 323869



Photo #9823 From entrance to location.



Photo #9824 From entrance to location.

Stormwater Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /21SWSW
Location #: 323869



Photo #9825 Location lacks stabilization.



Photo #9826 Location lacks stabilization.

Stormwater Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /21SWSW
Location #: 323869



**Photo #9831 Insufficient tracking BMP at entrance
to location.**