

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOGAN STREET
DENVER, COLORADO 80203



WILLIAM R. SMITH
Director

FRANK J. PIRO
Deputy Director

(303) 866-3531

RICHARD D. LAMM
Governor

July 31, 1986

BHP Petroleum Inc.
P.O. Box 3280
Casper, WY 82601

RE: Bear Victor 4-13; NWNW 13,6N,87W, Routt Co. CO

Dear Sirs,

On July 23, 1986, I inspected the wellsite mentioned above for a final P&A inspection. As of that date the final restoration work had not been done. Usually we allow approximately a year for restoration work to be completed to allow for adequate time for the pits to dry. I wanted to inform you that the road to the location is quickly deteriorating and your prompt attention to this matter will prevent the necessity of rebuilding the road.

If you have any questions, please contact this office.

Sincerely,

Katy Templeton-Buell
Petroleum Engineer

LOCATION NW1/4 6N, 87W
OPERATOR BHP
WELL NAME Bear Victor 4-13

FIELD Bear River
COUNTY Roott
FORMATION _____

DATE OF INSPECTION DURING DRILLING: _____

RIG _____ SURFACE CASING: _____
BOP'S _____ DEPTH _____ WOC _____
CONTACT _____ CMT VOL _____ RETURNS _____
ADEQUATE AQUIFER PROTECTION? _____
COMMENTS _____

DATE OF INSPECTION AFTER COMPLETION: _____

FRACED: _____ PRODUCTION STRING: _____
CBL CHECKED? _____ DEPTH _____ STAGED _____
WATER DISPOSAL METHOD _____
PITS: PERMIT _____ TDS _____ SKIM TANK _____
DIMENSION: _____ SCREEN: _____ LINER: _____

LEASE SIGN: _____ TANK ID: _____ FENCED? _____
SURFACE EQUIPMENT: _____

DATE OF FINAL P&A INSPECTION 7/23/86

PLUG 1 _____ SX @ _____ SURFACE RECLAIMED? NO
PLUG 2 _____ SX @ _____ SITE CLEAN? NO
PLUG 3 _____ SX @ _____ LANDOWNER RELEASE? _____

INSPECTOR KTB

plate welded over ~~the~~ surface casing. Celler,
pits are open. Surface restoration needs to
be done this summer before road
disintegrates.

Notice sent 7/31/86