

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/03/2023

Submitted Date:

05/03/2023

Document Number:

702501254

FIELD INSPECTION FORMLoc ID 315317 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Patterson, Chris		Chris.Patterson@scoutep.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Johnson, Mike		Mike.Johnson@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230625	WELL	SI	12/01/2021	OW	103-08293	LN HAGOOD A-15X	SI

General Comment:**COGCC Inspection Report Summary**

On Wednesday, 05/03/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Scout Energy Management LLC on the LN Hagood A-15X well, Location #315317, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority/NSO/Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to FIRR #403370792 submitted by Operator for Corrective Actions from Inspection #702501107 on 4/6/23.

While there during normal production operations the following compliance issue was observed:

1. Insufficient BMPs to control vehicle tracking.
2. Well sign lacking public road access information.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Wellhead sign lacking public road used to access location information		
Corrective Action:	When no associated Tank battery is present at the Oil and Gas Location, the following additional information is required on the Well sign: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Well; Well name(s) and API number(s); The legal location of the Well(s) including the quarter/quarter section.	Date:	07/15/2023
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-675-3700 or 911

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks on containments		
Corrective Action:		Date:	
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Accessible with valve.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	230625	Type:	WELL	API Number:	103-08293	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>Last Production - February 2023</div>									
Corrective Action: <div></div> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
				Material Handling And Spill Prevention		
		Ditches				
Berms						

Comment: [Insufficient BMPs to control vehicle tracking.](#)Corrective Action: [Oil and gas operators shall implement and maintain vehicle tracking Best Management Practices \(BMPs\) to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Date: 06/03/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403393436	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6103601
702501263	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6103594