


Gils hot oil service
State 5
Location # 324641



Tank battery lacking proper signage



location

Gils hot oil service
State 5
Location # 324641



Staining under valve on tank




Valve on tank lacking plug/cap

Gils hot oil service
State 5
Location # 324641



Insufficient secondary containment



No Braden head access

Gils hot oil service
State 5
Location # 324641



Pump jack is lacking guard



Guard for pump jack

