


# Stormwater Management and Erosion control

## Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /33NWSE.

### Location #: 334955



**Location Overview: The location is located in an intermediate 411 a. buffer zone.**

**Section/Township/Range: 33 6S95W**

**Stormwater Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /33NWSE.**  
**Location #: 334955**



**Photo #9964 Location lacks stabilization.**



**Photo #9965 Location lacks stabilization.**



**Stormwater Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /33NWSE.**  
**Location #: 334955**



**Photo #9964 Location lacks stabilization.**



**Photo #9967 Location lacks stabilization.**



**Stormwater Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /33NWSE.**  
**Location #: 334955**



**Photo #9968 Location lacks stabilization.**



**Photo #9969 Location lacks stabilization.**



**Stormwater Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /33NWSE.**  
**Location #: 334955**



**Photo #9973 Location lacks stabilization.**



**Photo #9972 Insufficient tracking BMP at entrance to minimize the transport of sediment.**