

Inspection Photos

5/15/2023

Operator: LARAMIE ENERGY LLC #10433 /
BLACK HILLS PLATEAU PRODUCTION LLC
#10150

Location Number: 312404
Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



Photo 3: Photo taken from the southeast end of the Location, facing west. Photo shows cut and fill slopes remain; Location has not been recontoured/regraded/reclaimed.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



Photo 4: Photo taken from the northwest end of the Location, facing west. Photo shows cut and fill slopes remain; Location has not been recontoured/regraded/reclaimed.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



Photo 5: Photo taken from the east end of the Location, facing north. Photo shows cut and fill slopes remain; Location has not been recontoured/regraded/reclaimed.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



Photo 6: Photo taken from the cut slopes on the northeast end of the Location. Cut slopes lack stabilization; erosion degradation and sediment transport observed.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



Photo 7: Photo taken from the cut slopes on the northeast end of the Location. Photo shows sediment deposition due to unstabilized cut slopes.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



Photo 8: Photo taken from the cut slopes on the northeast end of the Location. Photo shows sediment deposition due to unstabilized cut slopes.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



Photo 9: Photo shows cut and fill slopes remain; Location has not been recontoured/regraded/reclaimed. Vegetation observed on cut slopes predominantly Undesirable Plant Species, such as *Erodium cicutarium* and *Thlaspi arvense* (yellow flowered plant in photo right).

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



Photo 10: Photos examples showing Undesirable Plant Species observed on the cut slopes, such as such as *Erodium cicutarium* (photo left) and *Thlaspi arvense* (photo right).

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



Photo 11: Photo show soil stockpile remaining on the Location. Segregated soils have not been replaced to their relative original position and grade.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



Photo 12: Photo shows unused pipe equipment remaining on the northwest end of the Location.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



Photo 13: Photo shows what appears to be cement debris remaining on the south end of the Location.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



May 15, 2023



May 15, 2023

Photo 14: Photo shows unused cable equipment remaining on the southern end of the Location.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433 / BLACK HILLS PLATEAU PRODUCTION LLC #10150

Location Number: 312404



Photo 15: Photos examples showing the access road leading to the Location has not been reclaimed pursuant to Rule 1004; gravel/road base remains, access road has not been decompacted, recontoured/regraded and reclaimed.