

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403403689

Date Received:

05/15/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10267

Name of Operator: VECTA OIL & GAS LTD

Address: 575 UNION BLVD #208

City: LAKEWOOD State: CO Zip: 80228

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Goolsby, Mathew

303-618-7736

matgoolsby@vecta-denver.com

Beardslee, Tom

tom.beardslee@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 690204064

Inspection Date: 04/06/2023

FIR Submit Date: 04/07/2023

FIR Status: _____

Inspected Operator Information:

Company Name: VECTA OIL & GAS LTD

Company Number: 10267

Address: 575 UNION BLVD #208

City: LAKEWOOD State: CO Zip: 80228

LOCATION - Location ID: 481718

Location Name: Sammons Number: 315310C County: LAS ANIMAS

Qtrqr: NESW Sec: 10 Twp: 31S Range: 53W Meridian: 6

Latitude: 37.355100 Longitude: -103.350590

FACILITY - API Number: 05-071- -00 Facility ID: 482139

Facility Name: Sammons Number: 315310C

Qtrqr: NESW Sec: 10 Twp: 31S Range: 53W Meridian: 6

Latitude: 37.355100 Longitude: -103.350590

CORRECTIVE ACTIONS:

1 ☒ CA# 169166

Corrective Action: Install sign to comply with Rule 605.a.

Date: 08/06/2022

Response: CA COMPLETED

Date of Completion: 05/10/2023

Operator Comment: (See photo attachment) Compliant well signs have been installed at lease entry and wellhead.

COGCC Decision: Approved

COGCC
Representative:

2 ☒ CA# 169167

Corrective Action: POST EMERGENCY CONTACT NUMBERS INCLUDING 911 PER RULE 605.

Date: 08/06/2022

Response: CA COMPLETED

Date of Completion: 05/10/2023

Operator Comment: (see photo attachments) Signs added at lease entry and wellhead with emergency contact number, including 911.

COGCC Decision: Approved

COGCC
Representative:

3 ☒ CA# 169168

Corrective Action: Comply with the 1003 interim reclamation rules.

Date: 03/19/2023

Response: CA COMPLETED

Date of Completion: 05/05/2023

Operator Comment: Wellhead enclosed with corral panels (100 sq ft). All debris and equipment removed. Silt barrier removed and barrier trench refilled. Well pad leveled, harrowed, reseeded and mulched.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 169169

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 03/01/2023

Response: CA COMPLETED

Date of Completion: 05/05/2023

Operator Comment: Silt fence and trench was removed and filled at surface owners request, and to facilitate reseeding, harrowing, and mulching.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: 1) This location could NOT be ripped to 18", due to thin topsoil and bedrock at or near ground surface. We reclaimed following the surface owners suggestions and requests, based on 120 years of family history on the land.
2) Well is under request for TA status while CO2 market is investigated.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mathew Goolsby

Signed:

Title: VP of Operations

Date: 5/15/2023 4:54:48 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403403689	FIR RESOLUTION SUBMITTED
-----------	--------------------------

403403795	Well Sign at entrance
403403803	Well sign at wellhead.
403403806	Photo after harrowing, reseeding, and mulching.

Total Attach: 4 Files