

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324154



SW Corner of Location – Photo #03511



NW Corner of Location – Photo #03512

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324154



NE Corner of Location – Photo #03513



SE Corner of Location – Photo #03514

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324154



Wellhead – Photo #03515

Separator – Photo #03520

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324154



Tank Battery – Photo #03521

Location Lacks Stabilization – Photo #03518

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324154



Location Lacks Stabilization – Photo #03523

Rill Erosion Transporting Sediment Across Access Road Entrance – Photo #03525

TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESW

Location #324154



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #03524**