

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 44-28 Pad
Location # 324009



**Location Overview: Location is approximately 210 yards from the
Colorado River**
Section/Township/Range: 28 6S94W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 44-28 Pad
Location # 324009



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 44-28 Pad
Location # 324009



Photo # 8226 Erosion & transport of sediment off location into vegetation/insufficient BMP's (NW corner of location)



Photo # 8227 Erosion & transport of sediment off location into vegetation/insufficient BMP's (NW corner of location)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 44-28 Pad
Location # 324009



Photo # 8228 Erosion & transport of sediment off location into vegetation/insufficient BMP's (NW corner of location)



Photo # 8229 Erosion & transport of sediment off location into vegetation/insufficient BMP's (NW corner of location)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 44-28 Pad
Location # 324009



Photo # 8230 Erosion & transport of sediment off location into vegetation/insufficient BMP's (NW corner of location)



Photo # 8231 Erosion & transport of sediment off location into vegetation/insufficient BMP's (NW corner of location)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 44-28 Pad
Location # 324009



Photo # 8232 Erosion & transport of sediment off location into vegetation/insufficient BMP's (South side of location)



Photo # 8233 Erosion & transport of sediment off location into vegetation/insufficient BMP's (South side of location)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 44-28 Pad
Location # 324009



Photo # 8234 Erosion & transport of sediment off location into vegetation/insufficient BMP's (South side of location)



Photo # 8235 Erosion & transport of sediment off location into vegetation/insufficient BMP's (South side of location)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 44-28 Pad
Location # 324009



**Photo # 8236 Erosion & transport of sediment off
location into vegetation/insufficient BMP's (South side
of location)**