

FORM  
INSPRev  
X/20

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2023

Submitted Date:

05/17/2023

Document Number:

690204228

**FIELD INSPECTION FORM**

Loc ID 324900 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 16520Name of Operator: CHEMCO INCAddress: 6970 SOUTH HOLLY CIR STE 206City: CENTENNIAL State: CO Zip: 80112**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments5 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Neher, Morgan		morgan@chemco-og.com	
Neher, Gray		gh.neher@chemco-og.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261201	WELL	PR	06/01/2020	OW	061-06782	BAUGHMAN 5A-2	RI

**General Comment:**

On 5/15/2023, Ryan Costa conducted a location and stormwater management inspection.  
See attached photos and additional details within this report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Vehicles are driving outside of the designated road boundary causing unnecessary disturbance.		
Corrective Action:	Immediately Comply with 1002.e. to restrict access to original access road boundry.	Date:	05/17/2023

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	There are oil stained soils at the base of the pumpjack that need to be cleaned up.		
Corrective Action:	Immediate clean up of stained soil. Implement or modify BMPs for improved material handling and spill prevention.	Date:	05/31/2023

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	Tank		
Comment:	There is a leak at the pipe outlets at the front and backside of the tanks. Stained soils need to be cleaned up and leak needs to be repaired.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 05/19/2023

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	<input style="width: 100%;" type="text"/>		
Other (Content)	<input style="width: 100%;" type="text"/>		
Other (Capacity)	<input style="width: 100%;" type="text"/>		
Other (Type)	<input style="width: 100%;" type="text"/>		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	The secondary containment berm is insufficient to contain a spill and needs to be rebuilt.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date:	07/07/2023

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There are vehicle ruts from vehicle driving outside of the access road boundry. Areas of rutting need to be repaired and stabilized.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 05/31/2023

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403406065	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6117576">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6117576</a>
690204229	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6117556">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6117556</a>