

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/22/2023

Submitted Date:

05/23/2023

Document Number:

690204246

FIELD INSPECTION FORMLoc ID 322228 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 44390

Name of Operator: JAVERNICK OIL

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Javernick, Salene		salenej@gmail.com	
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	
Beardslee, Tom		tom.beardslee@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210045	WELL	PR	05/01/2021	OW	043-06124	CONOCO - SANTA FE 1-6	RI

General Comment:

On 5/22/2023, Ryan Costa conducted a location and stormwater management inspection.
See attached photos and additional details within this report.

LocationOverall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Tank sign and labels appears to have been replaced.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			
Crude Oil	Tank				
Comment:	There is stained soils at the tank outlets at the backside of tank battery,.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.				Date: 06/10/2023

In Containment: Yes

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	The fence around the tank battery is not maintained.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	05/29/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion along the access road that needs to be repaired and stabilized with BMP's. The road has been washed out at the draiage crossing from a recent storm evennt. BMP's need to be installed at the drainage crossing such as an adequately sized culvert. There is also vehcile rutting at the location which is not compacted and stabilized.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 05/25/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403410883	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6123323
690204247	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6123313