

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403416979

Date Received:  
05/30/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204833

Inspection Date: 04/05/2023

FIR Submit Date: 04/06/2023

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 440705

Location Name: Watson Ranch B Pad Number: \_\_\_\_\_ County: \_\_\_\_\_

Qtrqr: SESW Sec: 17 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.433375 Longitude: -108.022682

FACILITY - API Number: 05-045-00 Facility ID: 440705

Facility Name: Watson Ranch B Pad Number: \_\_\_\_\_

Qtrqr: SESW Sec: 17 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.433375 Longitude: -108.022682

CORRECTIVE ACTIONS:

1 CA# 169112

Corrective Action: Comply with Rule 1003.b and conduct interim reclamation on areas of the Location not reasonably needed for production Operations.

Date: 04/30/2023

Response: CA COMPLETED

Date of Completion: 05/25/2023

Operator  
Comment:

TEP has performed interim reclamation on an additional 1.7 (+/-) acres of the pad that is not reasonably needed for production operations. Road base and gravel was stripped / removed from this portion of the pad. Underlying soils were then ripped, disked, and seeded with an appropriate seed mix approved by the owner. See attached pics. This corrective action is complete.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 169113

Corrective Action: Comply with 902 Rules, and 1002.f: Install or repair required BMPs.

Date: 03/06/2023

Response: CA COMPLETED

Date of Completion: 05/25/2023

Operator Comment: Pad surface has been bladed / graded smooth to remove ruts that developed during soft / muddy conditions. Storm water BMPs have been maintained as needed. This corrective action is complete.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Both corrective actions have been completed. See attached pics.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed:

Title: TEP Environmental Lead

Date: 5/30/2023 2:30:39 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403417041	Watson Ranch B - additional interim reclaim area
403417042	Watson Ranch B - drilled seed
403417063	Watson Ranch B Additional Reclaim Area - View North
403417066	Watson Ranch B Additional Reclaim Area - View East

Total Attach: 4 Files