

Operator: CRESTONE PEAK RESOURCES
Location Name: PURITAN 2N68W/34SESE
Loc ID: 336413
Inspection: 710100014



Exhibit A



Exhibit B

CA: Missing NFPA placard and labels on horizontal separator. Install signage to comply with Rule 605.h.

CA Resolution: Operator has appropriately installed NFPA labels to comply with Rule 605.h.



Exhibit A

CA: Inadequate fencing around excavation. Repair and maintain best management practices to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended. the site was not attended at the time of the inspection.

CA Resolution: Operator has appropriately addressed and fixed/installed adequate fencing around excavation to comply with Rule 913.b(5)B.i.