

# TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SESW

## Location #334826



**SE Corner of Location – Photo #04192**



**NW Corner of Location – Photo #04193**

# TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SESW

Location #334826



SW Corner of Location – Photo #04194



NE Corner of Location – Photo #04199



# TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SESW

Location #334826



Wellheads – Photo #04198



Separators – Photo #04200





# TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SESW

Location #334826



Tank Battery – Photo #04203



Cut Slope Eroding onto Location – Photo #04201



# TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SESW

Location #334826



Lease Road Lacks Stabilization – Photo #04210



Lease Road Lacks Stabilization – Photo #04212



# TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SESW

Location #334826



Insufficient Vehicle Tracking BMPs – Photo #04214



Insufficient Vehicle Tracking BMPs – Photo #04215