

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad
Location # 335160



Location Overview:
Section/Township/Range: 16 6S94W

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad
Location # 335160



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad
Location # 335160



Photo # 9722 Ditch needs maintenance/erosion within inches of earthen tank battery containment



Photo # 9723 Erosion within inches of earthen tank battery containment

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad
Location # 335160



Photo # 9725 Erosion within inches of earthen tank battery containment



Photo # 9727 Erosion within inches of earthen tank battery containment

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad
Location # 335160



Photo # 9728 Ditch/check dams/culvert needs maintenance



Photo # 9730 Ditch/check dams/culvert needs maintenance

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad
Location # 335160



Photo # 9731 Ditch/check dams/culvert needs maintenance



Photo # 9733 Culvert needs maintenance

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad
Location # 335160



Photo # 9734 Ditch & Check dams need maintenance/erosion near fence & earthen tank battery containment



Photo # 9735 Ditch & Check dams need maintenance/erosion near fence & earthen tank battery containment

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad
Location # 335160



Photo # 9736 Ditch & Check dams need maintenance/erosion near fence & earthen tank battery containment



Photo # 9737 Ditch & Check dams need maintenance/erosion near fence & earthen tank battery containment

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad
Location # 335160



**Photo # 9739 Erosion near tank battery
containment**



**Photo # 9740 Erosion near fence & tank battery
containment**

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad
Location # 335160



Photo # 9741 Culvert needs maintenance



Photo # 9743 Culvert needs maintenance

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC RMV 4-16 Pad
Location # 335160



Photo # 9745 Culvert needs maintenance