

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/26/2023

Submitted Date:

06/02/2023

Document Number:

708200313

**FIELD INSPECTION FORM**

Loc ID: 435421    Inspector Name: Edwardson, Dylan    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96155  
Name of Operator: WHITING OIL & GAS CORPORATION  
Address: 1700 LINCOLN STREET SUITE 4700  
City: DENVER    State: CO    Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
TRUITT, J CODY	281-513-0697	ctrutt@fundareresources.com	Principal Agent
CO, Eastern		WhitingEasternCO@Whiting.com	All Eastern CO Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435421	LOCATION	AC			-	Razor 26 Production	RI

**General Comment:**

This is an Interim Reclamation and Stormwater Inspection for Location ID 435421.

COGCC records indicate the current Operator of Record for this location (435421) is "Whiting Oil and Gas Corporation-96155". "Fundare Resources Operating Company LLC-10773" also has an active/open Remediation Project (#29346) on this location (435421). Both Operators are being notified in the event that this location has been transferred to another Operator and was not properly documented with COGCC. If this location has in fact been transferred, Operators shall complete appropriate forms for "Transfer of Operatorship" pursuant to Rule 218.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment: Stained soil observed on the southern end of the location, south of compressors. Refer to attached inspection photos.

Corrective Action: Properly dispose of oily waste in accordance with 905.e. Corrective action date is the date the location was observed out of compliance.

Date: 05/26/2023

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type

OTHER

Comment: Perimeter fencing around open excavation associated with Remediation Project #29346 appears inadequate to exclude wildlife entry.

Corrective Action: Install or repair wildlife protection equipment per Rule 902.b. Corrective action date is the date the location was observed out of compliance.

Date: 05/26/2023

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 435421 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**Environmental**

**Spill/Remediation:**

Comment: [Remediation Project #29346 is still active and open. Continue to comply with 900 series rules and regulations.](#)

Corrective  
Action:

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_

Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? **Fail**

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment This location does not comply with Rule 1003. During this inspection, Staff observed that the western interim areas do not appear to be progressing towards Rule 1003 standards as areas of non-uniform vegetation cover were evidenced by bare soil. Additional reclamation activities are required to meet Rule 1003 standards. Refer to attached inspection photos for documentation.

Corrective Action Perform reclamation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards. Corrective action date is the date the location was observed out of compliance.

Date 05/26/2023

Overall Interim Reclamation Fail

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location

Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: This location does not comply with Rule 1002.f. Staff observed that apparent impacted material being stored on the north end of the location, possibly associated with Remediation Project #29364, was not placed on a impervious liner and sediment control logs appeared inadequate with evidence of sediment transport outside of BMPs. More robust BMPs will need to be implemented to prevent impacted material from migrating outside of containment. Refer to attached inspection photos for documentation.

Corrective Action: Comply with Rule 1002.f.(2)B and implement or modify BMPs for improved material handling and spill prevention. Corrective action date is the date the location was observed out of compliance.

Date: 05/26/2023

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403422511	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6135137">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6135137</a>
708200314	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6133710">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6133710</a>