

FORM

6

Rev  
11/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

DE


ET


OE

ES

Document Number:  
  
403425431

Date Received:





WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number:100322

Contact Name:Gina Arcila

Name of Operator:NOBLE ENERGY INC

Phone:(432) 202-5717

Address:2001 16TH STREET SUITE 900

Fax:

City:DENVERState:COZip:80202

Email:gina.arcila@chevron.com

For "Intent" 24 hour notice required,

Name:Petrie, EricaTel:(303) 726-3822

COGCC contact:Email:erica.petrie@state.co.us

Type of Well Abandonment Report:☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

API Number05-123-20778-00

Well Name:FEDERAL PALOMINOWell Number:11-13

Location:QtrQtr:NESWSection:13Township:8NRange:59WMeridian:6

County:WELDFederal, Indian or State Lease Number:C-28082 ACQ

Field Name:LILLIField Number:49970

Only Complete the Following Background Information for Intent to Abandon

Latitude:40.658500Longitude:-103.926830

GPS Data:GPS Quality Value:6.0Type of GPS Quality Value:PDOPDate of Measurement:03/16/2006

Reason for Abandonment:☐ Dry☒ Production Sub-economic☐ Mechanical Problems

☐ Other

Casing to be pulled:☐ Yes☒ NoEstimated Depth:

Fish in Hole:☐ Yes☒ NoIf yes, explain details below

Wellbore has Uncemented Casing leaks:☐ Yes☒ NoIf yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
D SAND	6537	6547			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J55	24	0	585	410	585	0	VISU
1ST	7+7/8	4+1/2	J55	11.6	0	6764	225	6764	5720	CBL

Date Run: 6/15/2023 Doc [#403425431] Well Name: FEDERAL PALOMINO 11-13

Page 1 of 3

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6487 with 2 sacks cmt on top. CIBP #2: Depth 5775 with 2 sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 35 sks cmt from 2249 ft. to 1849 ft. Plug Type: CASING Plug Tagged: ☐  
Set 60 sks cmt from 785 ft. to 0 ft. Plug Type: CASING Plug Tagged: ☒  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at 2349 ft. with 155 sacks. Leave at least 100 ft. in casing 2249 CICR Depth

Perforate and squeeze at 785 ft. with 190 sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged: ☐

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing

Surface Plug Setting Date: \_\_\_\_\_ Cut and Cap Date: \_\_\_\_\_ Number of Days from Setting Surface Plug to Capping or Sealing the Well: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_

\*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

This well is part of the AOC (Order 1V-668) Alt MIT program.

3rd party wildlife surveys will be conducted on this well prior to rigging up for P&A activities.

Notification will be given to any adjacent building unit occupants within a 1000 feet of the wellhead of planned P&A start date.

Please be aware that Form 6 Approval can predate actual rig work by up to several months and that environmental conditions can change quickly over that time. Chevron's Environmental Site Screening Process incorporates full environmental field clearances within 7 days of a scheduled well-work activity once the well is added to the active workover rig schedule. Should sensitive HPH conditions be identified during the screening process, Chevron will delay the work until conditions (nesting) clear and/or consult directly with CPW for guidance and discussion of potential mitigation measures that may be incorporated.

No CPW consult required.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_

Print Name: Sharon Strum

Title: Lead Wells Technical

Date: \_\_\_\_\_

Email: sharon.strum@chevron.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

Expiration Date: \_\_\_\_\_

<u>COA Type</u>	<u>Description</u>
0 COA	

### Attachment List

<u>Att Doc Num</u>	<u>Name</u>
403435598	WELLBORE DIAGRAM
403435600	WELLBORE DIAGRAM

Total Attach: 2 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	<ul style="list-style-type: none"> <li>- Verified as drilled Lat/Long</li> <li>- Verified Completed Interval (1110289)</li> <li>- Missing DSND production report for the month of 01/2012 - notified operator</li> </ul> <p>Emailed operator for the following:</p> <ul style="list-style-type: none"> <li>- Return to DRAFT - Confirm/Correct Completed Formation; Update WBD</li> </ul>	06/15/2023

Total: 1 comment(s)