

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2023

Submitted Date:

06/14/2023

Document Number:

702501451

FIELD INSPECTION FORMLoc ID 316300 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS State: CO Zip: 80129

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Adams, Karen	(303) 886-8733	adams@kt-res.com	
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Baumgras, Dan	(307) 321-3299	Dan@KT-Res.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261061	WELL	SI	10/01/2020	GW	103-10193	WRD DOW 20-13	SI

General Comment:**COGCC Inspection Report Summary**

On Wednesday, 06/14/2023, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the WRD Dow 20-13 Well, Location #316300, in Rio Blanco County, Colorado.

This location is within or in close proximity to a CPW District with Black Bear, High Priority, NSO, Density and Other Consultation Habitat Regulations.

Any Corrective Actions from previous Inspections are still applicable.

Several Corrective Actions from Inspection #707800288 on 4/11/23 have not been corrected.

While there during normal operations the following compliance issues were observed for the 2nd time:

1. Stained soils.
2. Equipment open to wildlife.
3. Insufficient Stormwater BMPs.
4. Gas meter calibration not visibly displayed.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	When wellhead sign is replaced add API Number to sign information as required		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Production tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Faded and illegible labels on chemical tank		
Corrective Action:	Containers that are used to store, treat, or otherwise handle a hazardous material and which are required to be marked, placarded, or labeled in accordance with the U.S. Department of Transportation's Hazardous Materials Regulations, will retain the markings, placards, and labels on the Container. Such markings, placards, and labels will be retained on the Container until it is sufficiently cleaned of residue and purged of vapors to remove any potential hazards.	Date:	06/25/2023

Emergency Contact Number:

Comment: (800) 288-0560 or Call 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Separator stack open to wildlife		
Corrective Action:	Install or repair wildlife protection equipment.	Date:	06/25/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	
Crude Oil	Tank	<= 1 bbl	
Comment:	Oily waste and stained soil at loadline pot		
Corrective Action:	Remove and properly dispose of oily waste and impacted soils.		Date: 06/30/2023

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Accessible with valves		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration not visibly displayed.		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.		Date: 06/25/2023
Type: Ancillary equipment	# 1		
Comment:	Chemical tank in containment		
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	HEATED STEEL AST		,
Comment:	Loadline and tank valves have caps or plugs installed.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:	All tank valves have caps or plugs installed.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment: Unlined					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 261061 Type: WELL API Number: 103-10193 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment:

Last Production - September 2020

Well is overdue for Mechanical Integrity Test (MIT). MIT requires 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years.

COGCC engineering working with operator.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Stormwater BMPs need implementation and maintenance.](#)

Corrective Action: [Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Date: 06/30/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403434201	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6147709
702501452	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6147703