

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/21/2023

Submitted Date:

06/21/2023

Document Number:

702501499

## FIELD INSPECTION FORM

 Loc ID: 315082 Inspector Name: Burchett, Kirby On-Site Inspection:  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**
 OGCC Operator Number: 10779  
 Name of Operator: SCOUT ENERGY MANAGEMENT LLC  
 Address: 13800 MONTFORT DRIVE SUITE 100  
 City: DALLAS State: TX Zip: 75240
**Contact Information:**

Contact Name	Phone	Email	Comment
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Johnson, Mike		Mike.Johnson@scoutep.com	
Patterson, Chris		Chris.Patterson@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230226	WELL	TA	04/24/2018	OW	103-07885	CHEVRON FEE 103X	TA

**General Comment:**[COGCC Inspection Report Summary](#)

On Wednesday, 6/21/2023, Inspector Kirby Burchett, conducted a routine field inspection at Scout Energy Management LLC while on location to witness a scheduled Mechanical Integrity Test on the Chevron Fee 103X well, Location #315082, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Passing MIT losing 4 psi in 15 minutes from 510 psi to 506 psi.

No follow up inspection is required.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 230226 Type: WELL API Number: 103-07885 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Mechanical Integrity Test  
Packer set @ 5689'.  
Weber perforations 5792'-6438'.  
Initial tubing – 1050 psi. Production casing– 0 psi. Surface casing – 0 psi.  
Test Production casing to 510 psi.  
5 min – 507 psi. 10 min – 506 psi. 15 min – 506 psi. Pressure loss – 4 psi.  
Final tubing – 1140 psi. Surface casing –0 psi.  
MIT passed to maintain SI/TA status.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Ditches						

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501514	Form 21	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6156424">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6156424</a>
702501515	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6156425">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6156425</a>