

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403426674

Date Received:

06/07/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Victoria Dizghinjili

Phone

303-825-4822

Email

vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697602103

Inspection Date: 06/06/2023

FIR Submit Date: 06/07/2023

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqr: NWS Sec: 21 Twp: 2N Range: 68W Meridian: 6
W

Latitude: 40.123447 Longitude: -105.013035

FACILITY - API Number: 05-123- -00 Facility ID: 482194

Facility Name: Stromquist 4A Number: _____

Qtrqr: NWS Sec: 21 Twp: 2N Range: 68W Meridian: 6
W

Latitude: 40.123447 Longitude: -105.013035

CORRECTIVE ACTIONS:

1  CA# 172309

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.

Date: 06/09/2023

Response: CA COMPLETED

Date of Completion: 06/07/2023

Operator Comment: KPK is aware of the high rainwater at this open excavation site. The site is located in close proximity to Eagle's nest so all site activity has been suspended to comply with the COGCC CPW requirements. On 6/1/2023, KPK was granted short term variance to use a vacuum truck to lower the elevation of the water in the excavation. The water removal occurred that same day and removed 3 truckloads of water from the excavation. Water with a

sheen was removed at that time. KPK is willing to revisit the site if the COGCC and CPW will remove the access restrictions that protect the Eaglets

COGCC Decision: **Not Approved**

COGCC Representative: Operator has not proposed any fledgling monitoring or remedial action plan once eagles fledge, therefore this corrective action cannot be approved.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: John D Peterson

Signed:

Title: Engineering Tech

Date: 6/7/2023 5:15:43 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403426674	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files