

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/27/2023

Submitted Date:

06/27/2023

Document Number:

708300641

FIELD INSPECTION FORM

Loc ID 312553 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Findings:

- 6 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Byers, Jim		jbyers@blm.gov	
ENERGY, VISION		mco@visionenergy.biz	

General Comment:

[COGCC Inspection Report Summary](#)

On 6/27/2023 at approximately 10:30, Compliance Inspector Matthew Morris conducted an on-site inspection at VISION ENERGY LLC, LIPAN WASH-U2N2W/16NESW at Location ID #312553 in Mesa County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Wildlife entry hazard
- 2) Debris on location
- 3) Storage of unused equipment on location
- 4) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris on location.		
Corrective Action:	Remove debris from location to comply with Rule 606.	Date:	07/04/2023
Type	OTHER		
Comment:	Wildlife entry hazard present on west side of stored separator.		
Corrective Action:	Install wildlife protective equipment or remove hazard to comply with Rule 608.a.	Date:	07/02/2023
Type	STORAGE OF SUPL		
Comment:	Unused separator stored on location.		
Corrective Action:	Remove unused equipment from location.	Date:	07/27/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:	<input type="text"/>		
Corrective Action:		Date:	

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					Unprotected soil stockpiles

Comment: [Unprotected soil stockpiles on location.](#)

Corrective Action: **Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.**

Date: 07/12/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708300642	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6162806