

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2023

Submitted Date:

06/29/2023

Document Number:

702501585

**FIELD INSPECTION FORM**

Loc ID 315060 Inspector Name: Burchett, Kirby On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
16 Number of Comments  
6 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 10539  
 Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
 Address: 760 HORIZON DRIVE STE 400  
 City: GRAND JUNCTION State: CO Zip: 81506

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections	(970) 675-7928	inspections@utahgascorp.com	
Bleil, Rob	(970) 290-2912	rbleil@utahgascorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230182	WELL	SI	08/01/2022	OW	103-07841	GOVERNMENT C18983 6-1	SI

**General Comment:**

On Thursday, 6/29/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Utah Gas Op Ltd dba Utah Gas Corp on the Government C18963 6-1 well, Location #315060, in Rio Blanco County, Colorado. This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, and Density Habitat regulations. Location is also within a Public Water System (PWS) Protection area with Rule 411.a regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to FIRRs #403410606, 403414483, and 403433539 from Corrective Actions observed during Inspection #702501330 on 5/16/23. Not all Corrective Actions have been addressed.

While there during normal operations the following compliance issues were observed:

1. Debris.
2. Stained soil.
3. Weeds.
4. Unused equipment.
5. Unmarked anchor.
6. Insufficient Stormwater BMPs.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks labeled		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	970-693-6021 or 911		
Corrective Action:		Date:	_____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Out of service equipment storage. Chemical tanks, tank stairs and walkway.		
Corrective Action:	The storage, placement, or maintenance of equipment, vehicles, trailers, commercial products, chemicals, drums, totes, containers, materials, and all other supplies not necessary for use on an Oil and Gas Locations is prohibited.	Date:	07/15/2023
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	All trash, rubbish, and other waste material will be properly contained until removed from the Oil and Gas Location. At no time will trash, debris, or rubbish be placed or remain on the ground.	Date:	07/07/2023
Type	WEEDS		
Comment:	Weeds		
Corrective Action:	Maintain noxious weed control on all disturbed areas as a result of Oil & Gas activities.	Date:	07/07/2023

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	Treater	<= 1 bbl	
Comment:	Stained soil from vertical treater removal.		
Corrective Action:	Remove and properly dispose of oily waste and impacted soil.		Date: 07/15/2023

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Equipment:</b>		corrective date
Type: Horizontal Heater Treater	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 4	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 3	
Comment:	1 unmarked anchor due to Stormwater BMP maintenance.	
Corrective Action:	All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.	Date: 07/15/2023
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 4	
Comment:	Chemical tanks on containment. 2 tanks lack pumps and/or injection lines.	
Corrective Action:		Date:
Type: VRT	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Accessible	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		
Comment:	Loadline and tank valves have caps or plugs in place.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			

Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	HEATED STEEL AST		
Comment: All loadlines and tank valves are capped or plugged					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment: Unlined				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 230182 Type: WELL API Number: 103-07841 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Ditches				
				Material Handling And Spill Prevention		
Culverts						
Ditches						

Comment: Stormwater BMPs still need implementation and maintenance.

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 07/15/2023

Pits:  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501586	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6166193">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6166193</a>