

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403414200

Date Received:

05/26/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10701

Name of Operator: UPLAND EXPLORATION LLC

Address: 424 S MAIN ST

City: BOERNE State: TX Zip: 78006

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Rollins, Dustin

dustin@uplandexploration.com

Allison, Rick

rick.allison@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 697504676

Inspection Date: 05/16/2023

FIR Submit Date: 05/17/2023

FIR Status: _____

Inspected Operator Information:

Company Name: UPLAND EXPLORATION LLC

Company Number: 10701

Address: 424 S MAIN ST

City: BOERNE State: TX Zip: 78006

LOCATION - Location ID: 456651

Location Name: Salt Ranch Fee Number: 18 East County: _____

Qtrqtr: SESE Sec: 18 Twp: 11N Range: 64W Meridian: 6

Latitude: 40.914603 Longitude: -104.584484

FACILITY - API Number: 05-123- -00 Facility ID: 456651

Facility Name: Salt Ranch Fee Number: 18 East

Qtrqtr: SESE Sec: 18 Twp: 11N Range: 64W Meridian: 6

Latitude: 40.914603 Longitude: -104.584484

CORRECTIVE ACTIONS:

1 ☒ CA# 171090

Corrective Action: Identify spilled material and dispose in accordance with Rule 905 if spilled material is E&P Waste then submit a Form 19 Spill Report. If spilled material is not E&P Waste, cleanup spilled material and handle in accordance with Rule 906. Submit documentation of waste determination, disposal and reporting to CDPHE (if reportable quantity) using a Form 4 Sundry Notice. Notify Environmental Protection Specialist Rick Allison- rick.allison@state.co.us (970-461-2970)- prior to removal and disposal of waste.

Date: 05/16/2023

Response: CA COMPLETED

Date of Completion: 05/18/2023

Operator Comment: This was a non reportable spill of hydraulic fluid/oil; when a truck loading it had a hose rupture. The spill was less than 3 gallons of fluid, It was cleaned up and disposed of properly. See attached manifest.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed.

2  CA# 171091

Corrective Action: Comply with Rule 1002.f.

Date: 02/10/2023

Based on conversations with the Operator on May 11th, there is additional planned work, mainly an additional berm BMP to be installed along the western well pad. Therefore, the corrective action will remain open until the required BMPs are installed.

Response: CA COMPLETED

Date of Completion: 05/19/2023

Operator Comment: See document # 697504665; reclamation work has been on-going.

COGCC Decision: **Not Approved**

COGCC Representative: COGCC staff appreciates the update; however, COGCC has left this as an unresolved corrective action on a follow up inspection conducted on 4/7/2023- refer to Field Inspection Report Doc.# 697504722.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dustin Rollins

Signed:

Title: Field Supervisor

Date: 5/26/2023 7:05:55 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403414200	FIR RESOLUTION SUBMITTED
403414397	Manifest

Total Attach: 2 Files