

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2023

Submitted Date:

06/15/2023

Document Number:

697602110

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 \_\_\_\_\_ Ahmadian, Alexander \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
Anderson, Laurel		laurel.anderson@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478843	Flowline System	AC	12/17/2020		-	Facility 9	EI

**General Comment:**

COGCC environmental inspection for Spill ID 484569 in response to Complaint ID #403423164 associated with this spill reports "Oil and Gas on the surface from recent break in a vegetable field for human consumption". Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.



**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Inadequate		
Comment	Contaminated stockpile observed with no liner. COA on Doc #403423120 approved on 6/7/2023 states: "Initial report indicates cleanup was halted due to weather. Operator shall ensure that stormwater does not transport impacts outside of the spill footprint." Operator has not complied with this COA. All unaddressed COAs from previously approved Forms still apply. Operator shall submit photo documentation via FIRR once BMPs have been installed.			
Corrective Action	Implement or modify BMPs for improved material handling and spill prevention and properly dispose of oily waste in accordance with 905.e.			Date: 06/19/2023

**Spill/Remediation:**

Comment:	Stained soil seen along the route of the flowline and outside the secondary containment.		
Corrective Action:	In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.		
			Date: 06/19/2023

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
All unaddressed COAs from previously approved Forms still apply.	ahmadiaa	06/15/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403435487	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6149854">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6149854</a>
697602111	Complaint	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6149847">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6149847</a>
697602112	Photolog	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6149848">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6149848</a>