

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 40-20 Pad
Location ID: 335154



Location Overview: Location is approximately 47 yards from a drainage that contributes to the Colorado River. Location is within High Priority/Density Habitat areas.
Section/Township/Range: 20 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC RMV 40-20 Pad
Location ID: 335154



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.